







DS1 - EL
(Surface Mounted)





PRT - E
(Flush mounted)



Optional Remote Sensor



Setback Time Switch
Required to activate
4°C setback on DS1 - EL



UPONOR 230V CONTROL CENTRE

Switched Fuse Spur
3 Amp Fuse

Connect to Switch Live (A)